## FLORIDA AGRICULTURAL AND MECHANICAL UNIVERSITY

## **SOLE SOURCE CERTIFICATION**

	Requisition Number:	Bid #			
	authority granted under Florida A st to purchase the items(s) listed be		. , . , .	ing documentation is submitted	
Vendor: Coher	ent NA, Inc.				
Itoma(a).	Cost \$ 70400 Project 006804 It Laser System	9,550.00 Fund 203 Pgm 22			
	ribe efforts made, vendors contact relection). See attached for justifi		quired, availability,	compatibility,	
avail. Therefor work required	nade by the Co-PI and stree, Coherent, manufacture by the grant to support referred (DOE).	udents to restore the po rer of the laser system, esearch under the NNS	wer of the lase was contacted A-LANEM pro	er radiation emitted from the system to r I for the repair. Equipment is needed for ject. The funds have been approved by	the
I, the undersigned, cer	tify the above to be true and correct to  Associate  Title	o the best of my knowledge and beli Professor, Physics &	ief.  Co-Pl 3/4/ Date	<u>/25</u>	
delegated the author	esignee of the Florida A & M Unity as described in, hereby concurrement of the above as a solution	r {} do not concur {} with the	above justification	and recommend { } do not	
		Antonita E	Bryant	3/4/2025	
			urement Services	Date	
_	signee, acting for and on behalf of procurement of the above as a so	•	_		
		W. Kebewo VP, Administrati	u BY6WW ve and Financial Se	3/5/2025 ervices Date	
POSTED FROM _	03.18.2025 3:00PM	TO03.21.2025 3:00PM			
	DATE	TIME DATE	TIME		

FAILURE TO FILE A PROTEST WITHIN THE TIME PRESCRIBED IN REGULATION 6.005(9) (K), SHALL CONSTITUTE A WAIVER OF THE RIGHT TO PROCEEDINGS.



## Quote

Shipping Terms	Quote Date	Quote Number		
EXW	1/27/2025	COHR-332722-1		
Payment Terms*	Quote Expiration Date	Case Number		
Net 30	2/26/2025	C0791434		

Customer: Florida A&M University

James Strohaber

FL US

(979) 595-8494

james.strohaber@famu.edu

Send Purchase Order To: Coherent NA, Inc

40984 Concept Dr. Plymouth, MI 48170

naservice.admin@coherent.com Phone Number: (734) 456-3100,

Fax: (734) 416-1852

Please reference this quote number on your Purchase Order: COHR-332722-1

	Part Number	Description	Quantity	Unit Price	Extended Price
	1172919	Legend - Field Repair	12.00	US\$400.00	US\$4,800.00
	1364880	Field Service Travel Fee - < 10 hours (flight required) - North America SSC	1.00	US\$4,750.00	US\$4,750.00
Sub Total:				US\$9,550.00	
				Net Amount:	US\$9,550.00
				Total:	US\$9,550.00

<sup>\*</sup>Payment Terms referred to on quote are subject to approval. Exclusive of tax unless otherwise noted.

Coherent Standard Terms and Conditions Apply. Trade Terms refer to Incoterms 2020.

Coherent's "Terms and Conditions of Sale" are located at the following web link: Terms and Conditions of Sales

https://www.coherent.com/legal/terms-and-conditions-of-sale

THANK YOU FOR YOUR BUSINESS!

Adam Huss Customer Support Center 5100 Patrick Henry Dr SANTA CLARA, CA 95054 USA



Coherent Corp. 375 Saxonburg Blvd. Saxonburg, PA 16056-9499 USA

## **Sole Source Provider**

Coherent Inc. or Coherent certified service providers are the only businesses approved to perform field service, depot repairs, advance replacements, and return replacement events on Coherent manufactured equipment. Independent Service Providers (ISOs) are not recognized by Coherent and the following policy applies for Coherent products serviced by an ISO:

- Coherent recognizes the right of customers to utilize an ISO and does not intend to preclude ISOs from operating.
- Due to various safety, health, regulatory and other business considerations, Coherent will only
  distributes parts and components to customers or representatives that own Coherent equipment
- Customers have the option to install or have Coherent service install Coherent replacement parts with the understanding that some parts require Coherent-certified technical personnel to install them.
- Coherent disclaims any responsibility for maintenance or repair service performed by an ISO.
- Under standard terms and conditions of sale, customers should be advised that use of an ISO will
  void Coherent's warranty with respect to the operation of the customer's system or any
  component part thereof.
- No field service work will be performed by Coherent personnel on any Coherent laser system that
  has been serviced or intervened by an ISO until the scope of previous repairs or modifications
  has been understood by Coherent. This requires a written statement from the owner/end
  customer specifying the work previously completed. In addition, Coherent may request that the
  system be returned to its original condition and performance specifications via a depot repair
  strategy.
- Product support via telephone, email, and remote diagnostics if offered only to qualified Coherent customers.

coherent.com I T. +1 724 352 4455